

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 4757

DATE INSPECTED 6-18-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 823

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

125 ft.

7' Deep

WAS LATERAL AT CURB? Yes.

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Foundation not
started.

Approx. Bldg. Line

Approx. Curb Line



SIGNED

R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

Bernard Ave. S.W.

6-19-46 H.

REMARKS:

Lateral for lot 4650
used. House on 2 lots.

Nº 4757

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/18

RECEIVED OF Leo Kitz A. J. Diana

FEE OF 2

FOR WHICH PERMISSION IS GRANTED Leo Kitz

TO TAP San

SEWER, ON THE 75th

OF Bernard St.

AVE.
ST.,

TYPE OF STREET Alced

THE PREMISES BEING LOT NO. 116-49-4650

HOUSE NO. 823

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. J. Diana

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.