

Repair Job.

No 4761

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 6-29-46

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM Repair Job - See Sk

HOUSE NO. Rear 228 8th NE.


SIZE OF PIPE USED 4" DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. J. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4761

PERMIT TO TAP SEWER

MASSILLON, OHIO 6/27
RECEIVED OF Raymond Remley FEE OF \$ 2
FOR WHICH PERMISSION IS GRANTED Wm. Hupp
TO TAP Sanitary SEWER, ON THE East
OF Alley AVE., TYPE OF STREET dist
THE PREMISES BEING LOT NO. 1627 HOUSE NO. Rear 22#-8

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.