

Nº 4776

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-2-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1551

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

51' 8' Deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Rernley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Angler
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4776

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/31RECEIVED OF R RemleyFEE OF 2⁰⁰FOR WHICH PERMISSION IS GRANTED Wm KraftTO TAP SanSEWER, ON THE 7thOF 1st N EAVE., TYPE OF STREET PavedTHE PREMISES BEING LOT NO. 10156HOUSE NO. 1551

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.