

No. 4777

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-2-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1436

SIZE OF PIPE USED 6" UP 99' 7' Deep.
DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Diana NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



Last pipe laid
on approx. original
ground level in
Low spot.

No Excav. started.
Low Ground Here.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4777

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/12RECEIVED OF John C. A. [Signature]FEE OF \$ 2FOR WHICH PERMISSION IS GRANTED [Signature]TO TAP [Signature]SEWER, ON THE [Signature]OF [Signature]AVE.,
ST.,TYPE OF STREET [Signature]THE PREMISES BEING LOT NO. 12676HOUSE NO. 1436

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR [Signature]

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.