

Nº 4784

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-26-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

104

HOUSE NO. 1448

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

104

7' deep



WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Walnut Rd. S.W.



M.H.

104

7' deep

SIGNED

John E. Miller
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-10-46

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4784

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/26RECEIVED OF E. H. SmartFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED Don RousTO TAP Don RousSEWER, ON THE 72OF Walnut St.AVE.
ST.TYPE OF STREET AcadTHE PREMISES BEING LOT NO. 8829HOUSE NO. 1448

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.