

Nº 4791

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

195- 5'deep

HOUSE NO. 1721

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1324 ST. S.E.



SIGNED

John Ehrmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Tapped in main line

9/14/46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4791

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/10RECEIVED OF M. BluestoneFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED sameTO TAP SanSEWER, ON THE WOF 134th SEAVE., TYPE OF STREET dr
ST.,THE PREMISES BEING LOT NO. 4298HOUSE NO. 1721

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.