FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-12-4	FIRST MANHOLE DOWN STREAM 215' 8' dech
HOUSE NO. 1323	<u>보고 있</u> 다. 하는 사람들 사람들은 보통 등 다른 사람들은 사람들은 사람들이 되었다. 하는 사람들은 사람들은 사람들은 사람들이 되었다. 그 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들이 되었다. 그 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Blueslone.
SHOW BY DIAGRAM RELATION O	F LATERAL TO WALL OF BUILDING SERVED.
Woodland	(A/e, 55)
Burka balan barkan kangan yang bakil	Montre na de la compania de la comp
	But the state of t
SIGNED Whom Chan	FILED AT ENGINEER'S OFFICE 9/4/4/
INSPECTOR F	OR CITY
REMARKS:	

4793

Nº 4793 OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

्रेस्ट १ हुए। वस्तानक महत्वप्रशासक एम त स्व तन सेव	1/10
10 Blues	Massillon, Ohio,
FOR WHICH PERMISSION IS GRANTED	FEE OF SO
Jan Jan	A PARTA TA MARIATA PARTA
OF AVE. TY	PE OF STREET
THE PREMISES BEING LOT NO.	House No. /323

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNTY.
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MICHESTATION

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.