

Office room in Bay. of 17errall Garage

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o. 4799 AND SIGNED WHEN RETURNED

DATE INSPECTED 9-12-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM Tapped Main
under W. Walk 63'

HOUSE NO. 1005

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE OK. 10/3/46 D.

REMARKS:

Nº 4799

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/12

RECEIVED OF

Raymond Remley

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Stanford Indwell

TO TAP

Sanitary

SEWER, ON THE

West

OF

1st St E

AVE., TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

9708 - 45

HOUSE NO.

1005

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

R. Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.