

Nº 4803

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 9-16-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 147

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

247' 7' Deep.


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

1992
1745
247



SIGNED

R. E. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OK. 10/3/46 Do.

REMARKS:

This mess, came to end of lateral on Dot.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4803

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/16RECEIVED OF Raymond RemleyFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED SamTO TAP: 27th SESEWER, ON THE 7thOF Ave.

ST.,

TYPE OF STREET AlledTHE PREMISES BEING LOT NO. 3681HOUSE NO. 147

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.