

1
2

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
N^o 4813 AND SIGNED WHEN RETURNED

DATE INSPECTED 7-15-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

182

8' deep

HOUSE NO. 1520

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Forest Ave. S.E.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7/13/47

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4813

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/23RECEIVED OF M. BluestoneFEE OF \$2⁰⁰FOR WHICH PERMISSION IS GRANTED SameTO TAP SanSEWER, ON THE 7OF Forest St.AVE.,
ST.,TYPE OF STREET LeisTHE PREMISES BEING LOT NO. R 298-71HOUSE NO. 1520

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.