

1
2
1

N^o 4818

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-28-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 225 16' deep

HOUSE NO. 1432

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Forest Ave. S.E.



SIGNED John Ehrmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9/13/47

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4818

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/30

RECEIVED OF M. Bluestone

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER, ON THE 77

OF Forest St. E.

AVE., TYPE OF STREET dirt

THE PREMISES BEING LOT NO. R298-66

HOUSE NO. 1432

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.