

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4819

DATE INSPECTED 7-28-47

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 185- 18-deep

HOUSE NO. 1428

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH _____

SIZE OF PIPE USED 6


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Forest Ave. S.E.



SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9/13/47

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4819

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/23RECEIVED OF M. BluestoneFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED as perTO TAP SanSEWER, ON THE W.OF Forest St. E.AVE.,
ST.,TYPE OF STREET dirtTHE PREMISES BEING LOT NO. Q 298-65HOUSE NO. 1428

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.