

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 4820

DATE INSPECTED 7-22-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

145'

20' deep

HOUSE NO. 1424

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR


Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Forest Ave. S.E.



0 145



SIGNED

John Chamer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/13/47

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4820

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/23 1RECEIVED OF M. BluestoneFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED sameTO TAP SanSEWER, ON THE M.OF Forest St. E.AVE.,
ST.,TYPE OF STREET dirtTHE PREMISES BEING LOT NO. 1/2 298-64HOUSE NO. 1424

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.