## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-15-47	_ IF SO HOW AND LOCATION FROM 99 13 1666
HOUSE NO	마는 것은 경우 등에 가는 것이 되었다. 그런 그런 경우 전에 되었다. 그런
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE CONTROL OF THE CONTROL OF T
WAS LATERAL AT CURB? WAS ATTACHED TO MAIN	NAME OF CONTRACTOR BIVES Tone
<u>MMgagalidi</u> Miladahad medagungi kanangan sebuah mesebagai Amatat sebingga terbesah medi. Akit teri 1919 pe	ATERAL TO WALL OF BUILDING SERVED.
	JE 77
jeido kaj api se sieka kilo zist lob	2000 2000 2000 2000 200 200 200 200 200
SIGNED John Ehm	FILED AT ENGINEER'S OFFICE 9/13/47
REMARKS:	Transferred and dependence of problems in a classes

 $N_{0}$ 

4827

## Nº 4827

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	MASSILLON, OHIO,
	RECEIVED OF THE OF STATE OF ST
R	
	TO TAP SEWER, ON THE
	OF AVE. TYPE OF STREET
	THE PREMISES BEING LOT NO. 1298-57, HOUSE NO. 1381
	Work to be done in accordance with Ordinance No. 2323, buly passed by the City Counc
	RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.

1. (Theedone