

13
12
11
10
9
8
7
6
5
4
3
2
1

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o. 4829

DATE INSPECTED 7-15-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 17

HOUSE NO. 1332

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 17

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.


Forest Ave. S.E.



M.H.



17



SIGNED

John Chimer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7/13/47

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4829

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/23RECEIVED OF M. BluestoneFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED sameTO TAP SanSEWER, ON THE W.OF Fairch StAVE., TYPE OF STREET DistTHE PREMISES BEING LOT NO. 94 298 - 55HOUSE NO. 1332

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR M. Bluestone

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.