

Notes: - For rental charge add to present billing rate
one additional floor drain.

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4830

DATE INSPECTED 9-20-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. (?)

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

See Sketch

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Trap installed
just outside of
pit wall and riser
brought up two feet
and capped.



6"x4" Y cut
to 6" Existing
line to office
4" line run to
scale pit.

Existing 6"
Lateral

SIGNED

INSPECTOR FOR CITY

R. F. Snyder

FILED AT ENGINEER'S OFFICE

OK 10/3/46 De

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4830

PERMIT TO TAP SEWER

MASSILLON, OHIO.

9/23

RECEIVED OF

Raymond Remley

FEE OF \$

2⁵⁰

FOR WHICH PERMISSION IS GRANTED

Massillon Iron Structure

TO TAP

sanitary

SEWER, ON THE

south

OF

trunk line

AVE.,

TYPE OF STREET

ST.

THE PREMISES BEING LOT NO.

O L 136

HOUSE NO.

off Walnut

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.