

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4833

DATE INSPECTED 9-25-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 226

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

19' From E. curb line

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN


NAME OF CONTRACTOR

Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

3 RD ST. N.E.

N.



SIGNED

John Ehmer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

OT 10/18/46 Doc

REMARKS:

connected to house lateral in alley. 19' from curb

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4833

PERMIT TO TAP SEWER

MASSILLON, OHIO, 9/26 11RECEIVED OF Alice HellineFEE OF \$ 2.00FOR WHICH PERMISSION IS GRANTED SameTO TAP SanSEWER, ON THE EOF 3rd N.E.AVE., TYPE OF STREET Paved
St.THE PREMISES BEING LOT NO. 573HOUSE NO. 226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR P. Remley

Note. This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.