

Nº 4842

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-2-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 313

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURBLINE AND DEPTH

at back of side walk
100 ft 8' Deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Existing lateral run
into back edge of
Side walk



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OK. 12/5/46

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4842

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/19 11

RECEIVED OF Carl F Heckenbern

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED same

TO TAP San

SEWER, ON THE St

OF 15th St

AVE., TYPE OF STREET Alled

THE PREMISES BEING LOT NO. 8630

HOUSE NO. 313

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R Remler

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.