

Relay Job

No. 4846

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-25-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 131

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? See Sketch


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

8" Sewer under S. Walk
on Tremont S.W.

Existing lateral
sealed off. Too
high in basement



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Coal bunker of this bldg. extends out under
walk. Sewer tapped under floor of bunker.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4846

PERMIT TO TAP SEWER

MASSILLON, OHIO

10/25

RECEIVED OF

Raymond Remley

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

C. O. Finklebrock

TO TAP

Sanitary

SEWER, ON THE

South

OF

Tremont Ave. St.

AVE. ST.

TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

1794 1095

HOUSE NO.

131

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.