No	MOME
TAO	4847

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED



DATE INSPECTED 12-3-46 HOUSE NO	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
p "	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	Participation of the state of t	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		

See Sketch on 82" x 11" Sheet

SIGNED FILED AT ENGINEER'S OFFICE 12/5/4/6	OF (
INSPECTOR FOR CITY		FILED AT ENGINEER'S OFFICE 12/5/4/6
assurate of discrimination is subject to Place look of the land of	INSPECTOR FOR CITY	ut tociclus si vaiblind to alless

Nº 4847

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

Maria
MASSILLON, OHIO, 194
RECEIVED OF Chame lain It
FEE OF \$
FOR WHICH PERMISSION IS GRANTED Chymles Comments of the Commen
TO TAP Sanitary
TO TAP SEWER, ON THE SIDE
OF In I and E + Ventage
OF AVE. TYPE OF STREET DAY
THE PREMISES BEING LOT NO. 1492 HOUSE NO. 1219
WORK TO BE DOWN IN
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2223. DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.

Sketch for permits # 4847 and # 4848 R. Remtey - Contr. Insp. 12-3-46 R. F. Smyder Storm Drain 11-6" Deep at Bldg. "Pipe Storm Lines Roof Drains Hew. Catch Basin Acme Dairy San. M.H. Plant. 10'Deep > storm Sewer on W. Edge of MiH. 6'Deep Lincoln Way E. = Exist. 8" San. Sewer 2-6" Existing 12"Storm Sewer behind Curb 8 Conn.