## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 12-3-46          | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM |
|---------------------------------|---|
| HOUSE NO. 1219                  | DISTANCE FROM FIRST MANHOLE                           |
| SIZE OF PIPE USED 8 8 6         | DOWN STREAM TO DITCH AT CURB LINE AND DERTH           |
| WAS LATERAL AT CURB?            | NAME OF CONTRACTOR REMIEY                             |
| SHOW BY DIAGRAM RELATION OF LAT | ERAL TO WALL OF BUILDING SERVED.                      |
| See                             | 82×11" Sheet for sket                                 |
|                                 |   |

SIGNED FILED AT ENGINEER'S OFFICE 12/5/4/6

REMARKS:

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

|                              | one delle gran grant.   |
|------------------------------|-------------------------|
| RECEIVED OF A CAN            | MASSILLON, OHIO,        |
| FOR WHICH PERMISSION IS GRAN | NTED Clame / Warn Co    |
| TO TAP Storm                 | SEWER, ON THE           |
| or In Hay E                  | Wer Type of STREET Part |
| THE PREMISES BEING LOT NO.   | 1492 House No. 12/9     |

RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323. DULY PASSED

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.