

S.R. 7 R.3

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
Nº 4853 AND SIGNED WHEN RETURNED**

DATE INSPECTED 11-14-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 113

HOUSE NO. 2003

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 113' 7 1/2" deep

SIZE OF PIPE USED 6"


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Main. Ave. W.



SIGNED John E. Hester
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 11-15-46 TIME

REMARKS: _____

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4853

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/12

RECEIVED OF

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

OF

AVE. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.