## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-3-46	IF SO HOW AND LOCATION FROM	2+65 from Sippotr
HOUSE NO. 918		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR	Boger
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SE	RVED.  - 6
Delved victory values exploration of	5'-1"Dec	P) in 16-6" Deep
	Main Sewer in	Dead End Milli Z from Sippo Tru
SIGNED R.J. June 100 FOR	FILED AT ENGIN	<b>214</b>
REMARKS:	di najirahla at tangus di gaib	lisd to all 11/2-2/4/4

4855

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE DEPMIT TO TAP SEWER

	моля могассь был вром		11/1/generation
RECEIVED OF	D. L.	Massillon, Ohio,	FEE OF \$2
FOR WHICH PERMIS	ISION IS GRANTED	2 Cana	Anni ama ko azie Uzu ez sanzi ka caw
TO TAP	May Es	SEWER, ON THE	MOT CENDATTA BANGAN. Zinganeare ye penda Poliklipk
OF THE PREMISES BEIN	AVE. ST., g LOT NO. 1050	TYPE OF STREET, HOUSE N.	. 918
到了,就是一个人的一样的基础的一个"是个人的"。	IN ACCORDANCE WITH ORD	회에 살고 나는 말이 어떻게 하는 것이다. 어딘가 나는 것이다.	PABSED BY THE CITY COUNC

4855

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.