No. 4857 AND SIGNED WHEN RETURNED

DATE INSPECTED 10-2-46	IF SO HOW AND LOCATION FROM 1450 From Sippo T
HOUSE NO. 930	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? /Y &	
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR BOJEY
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
경향 전환자는 기업을 받는 것이다. 그런	
	√7'Deep
	4 Sept. 11 (15) 4 (14) 5 (14) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15) 6 (15)
Main	Sewer in L.
	Sewer in Theep 76
	Cstq. 1+50 from Sip
	。
SIGNED N.J. Smydu	FILED AT ENGINEER'S OFFICE

Nº 4857

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

	the state of the s
MA	SSILLON, OHIO. 11
RECEIVED OF	FEE OF S
FOR WHICH PERMISSION IS GRANTED SEWER, ON	THE
OF AVE. TYPE OF	PART OF THE PROPERTY OF THE PARTY OF THE PAR
THE PREMISES BEING LOT NO 1/2/2/3	그 것은 말은 어머니 나를 가는 때 사람이 없는 그 요즘 회사가 하는 것은 일을 때 때 모양 수 있었다.
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	
Rules of the Department of Public Service.	

Note. This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.