## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR & AND SIGNED WHEN RETURNED

DATE INSPECTED 12-7-46	IF SO HOW AND LOCATION FROM
HOUSE NO. $800$	FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE 232 6 DCGp
WAS LATERAL AT CURB? ソムム	- NAME OF CONTRACTOR RAY REWIEY
SHOW BY DIAGRAM RELATION OF L	ATERAL TO WALL OF BUILDING SERVED.
18101 0 f /ini	length : N = N = HOUSE = 38 7'Deep in ,
Curb 4	HOUSE = 38 7'Deep in Indeed E. Curb Line
Main	Sewer in Euclid S.W- 1 6' Deep
ISIGNED R.J. Jumple	FILED AT ENGINEER'S OFFICE 14/9/46
REMARKS:	iry a V. a - see heavy see a fill of the v. I believe A of footbeet a bound to rileve

 $N_0$ 

4864

## OFFICE OF THE DIRECTOR OF PUBLIC SERVICE 4864 PERMIT TO TAP SEWER

THE PERSON OF TH	MASSILLON, OHIO, / 11
and the second of the second o	, in the late of the first the late of the car like
RECEIVED OF	FEE OF \$
	The state of the s
FOR WHICH PERMISSION IS GRANTED	
TO TAP SEWER	, ON THE
OF AVE. TYP	E OF STREET
THE PREMISES BEING LOT NO.	HOUSE NO. X / O
THE PREMISES BEING CO. NO.	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANC	E NO. 2323. DULY PASSED BY THE CITY COUNCI
	[설프리스 크림하다 학교 교육학 중인국] - 현실 중인공설등록설증.

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.