FOLLOWING DATA TO BE ANSWERED BY INSPECTOR $N^{\rm o}_{\bullet}$ 4868 — and signed when returned

HOUSE NO. 1324		DOWN STREAM		
SIZE OF PIPE USED	DISTANCE FROM DOWN STREAM I CURB LINE AND		2VI2025	7 dech
WAS LATERAL AT CURB? No		elt vog mådelte i som og komune med det	e walawakon	
was attached to main No	NAME OF COL	NTRACTOR BLU	estan	
SHOW BY DIAGRAM RELATION C				
Marion Ave	- 5.6			14
				1700
		<u> 1905 (1964 follogist</u> Carlotte (1966)	erenkonik unt	
			and the second s	4/
	ever service of a variety of	eli A vo riserita deli i	Sarab Falus	6/1
		,. 2,	7:60	4/!
병을 하면 하고 있는 것, 그는 그는 그 이 스크를 하고 있다.	그리는 회사가 활성하는 사람들은 이 교육으로 📗 그는 회사는 김 학생들은 사람들이	N,H. ,	7	\$ / 14
			A STEEL STORY OF THE STORY OF T	
signed John Ehm				

4868 PERMIT TO TAP SEWER

		eder de 7s Mas:	sillon, Ohio,	11/30	1
RECEIVED OF	morning	, Blu	estone	FEE OF \$5	2 <u>~</u>
	ion is granted	网络沙漠 医皮肤性皮肤神经皮肤 化二甲烷二二甲烷二二甲烷二烷		tire	
	netard		propried the propried of the beauty of	with	
The first term of the control of the	m 12	es interesi la la britadore di la lor	down in Allows of All Sitts and the A	Anthropia (albanti Tharph) bandatikki	
TUE DREMICES BEING	LOT NO O A O	Z298	House No	1324	
and the first of the second of	N ACCORDANCE WITH RTMENT OF PUBLIC SE	그게 잘 받았는 아이는 것을 살았다.	2323. DULT PASS	ED BY THE COT	יסטאכ

NAME OF CONTRACTOR M (Shilstone

Note. This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.