

Nº 4873

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-5-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 91

HOUSE NO. 1529

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 91 7' deep


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Bluestone

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Marion Ave, S.E.



SIGNED John E. Humer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 1-6-47

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4873

PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/30

RECEIVED OF

In Bluestone

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

In Bluestone

TO TAP

sanitary

SEWER, ON THE

south

OF

Marion St.

AVE., TYPE OF STREET

dirt

THE PREMISES BEING LOT No.

Pt 10 L 298

House No.

1329

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

In Bluestone

Note. This permit covers work outside of building only. Any work in
 walls of building is subject to Massillon Board of Health Regulations.