

Reconstruction - not a new connection for building

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4881

DATE INSPECTED 12-18-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 140'

8'-6" Deep

HOUSE NO. 138

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 154'


8' Deep

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12/23/46

REMARKS:

This house cut off of existing line now serving 2 h
on Tremont and 2 on Second St. and is on own separate

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
N^o 4881
PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/11
RECEIVED OF A. L. Benedum FEE OF \$ 2.00
FOR WHICH PERMISSION, IS GRANTED A. L. Benedum
TO TAP sanitary SEWER, ON THE north
OF Dak Ave & E AVE., TYPE OF STREET paved
ST.,
THE PREMISES BEING LOT NO. 1005, HOUSE NO. 138

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.