

Relay of part of line

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR

Nº 4888

AND SIGNED WHEN RETURNED *Index She*

SEWER Record # 2

DATE INSPECTED 12-20-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 229

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 4

See Sketch


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Del. Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12/23/46

REMARKS:

Line relaid because of bad pipe and section 3\"/>

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4888

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/20

RECEIVED OF

Belcher Earley

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

Teton Lumber Co.

TO TAP

San

SEWER, ON THE

H

OF

1st & E

AVE. TYPE OF STREET

Paved

THE PREMISES BEING LOT NO.

329

HOUSE NO.

229

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Bel Earley

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.