

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4889

DATE INSPECTED

12-27-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Double

HOUSE NO.

134 - 136

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

6"

325'

7' Deep.

WAS LATERAL AT CURB?


Yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



15' x 5' Deep

6' x 7' Deep

Approx. N. Curb L.
Lake Ave. N.

Main Sewer

SIGNED

R. F. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

1-6-47

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4889

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/30

RECEIVED OF

Raymond Remley

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

E. H. Hosttler

TO TAP

Sanitary

SEWER, ON THE

north

OF

Lake Ave NE

AVE.,
ST.,

TYPE OF STREET

hard surface

THE PREMISES BEING LOT No.

6105

HOUSE No.

137-136

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.