

Nº 4891

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED.

DATE INSPECTED 12-28-46

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 3012

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes.

WAS ATTACHED TO MAIN Yes.

NAME OF CONTRACTOR Bemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Lincoln Way N. W.

SIGNED John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: Relaid 4'-6" pipe just off of stack.

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

Nº 4891

PERMIT TO TAP SEWER

MASSILLON, OHIO, 12/30

RECEIVED OF

J. H. Bailey

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

Raymond Remley

TO TAP

Sanitary

SEWER, ON THE

north

OF

Lin Hay RdAVE.
ST.

TYPE OF STREET

paved

THE PREMISES BEING LOT NO.

10202

HOUSE NO.

3012WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Raymond RemleyNote. This permit covers work outside of building only. Any work in
walls of building is subject to Massillon Board of Health Regulations.