

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

No. 4894

Relaid 3-9-55
DATE INSPECTED 11-19-46

DATE INSPECTED

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1835

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

From MH 2-177' 9' Dee

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

Boger Urban Ringley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Foundation not started



SIGNED R. J. Snyder

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

2-5-47

REMARKS:

House Not Built
Foundation dug - filled up by
order of Director Young by Diana
fall of 1950.

April 3-21-51 -
kateral (part) was relaid by Urban
3-9-55 *Thayer*

Nº 4894

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

Wm Heck

MASSILLON, OHIO,

1-7-49

RECEIVED OF

Ray T. Hines

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

San.

SEWER, ON THE

South

OF

Stoner

AVE.
ST.

TYPE OF STREET

Dirt

THE PREMISES BEING LOT NO.

8070

HOUSE NO.

1835

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

Urban

NAME OF CONTRACTOR

Boyer

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.