

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 4907

DATE INSPECTED 1-28-47

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** _____

HOUSE NO. 226

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** _____

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

14th ST. N.W.

N.



SIGNED John Chesser
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 2-4-47

REMARKS: Retard from curb line in.

Nº 4907

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 1/29

RECEIVED OF

Ramona Reardon

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Wm. Brough

TO TAP

Sanitary

SEWER, ON THE

East

OF

14th St NW

AVE.,
ST.,

TYPE OF STREET

Hard surface

THE PREMISES BEING LOT NO.

9822

HOUSE NO.

226

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Ramona Reardon

Note. This permit covers work outside of building only. Any work in walls of building is subject to Massillon Board of Health Regulations.