

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 1
Nº 4923 AND SIGNED WHEN RETURNED 28

DATE INSPECTED 3-31-47

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM Tapped main 87' from
UP up stream M.H.

HOUSE NO. 13

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH Main 12' Deep


WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

M.H. in Walk at
L. Way & 5th St.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 4/18/47 Doc

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4923

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/15RECEIVED OF Raymond RemleyFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED J. D. ConleyTO TAP SanitarySEWER, ON THE WestOF 5th St. N.W.AVE.,
ST.,TYPE OF STREET drivTHE PREMISES BEING LOT NO. Pl 429 + 431HOUSE NO. 13

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Raymond Remley

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.