

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 4962

DATE INSPECTED 7-28-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

78

HOUSE NO. 928

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

78

7' deep

WAS LATERAL AT CURB? Yes


WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

8TH ST. S.W.

N →



SIGNED

John Thayer

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9-12-47

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4962

PERMIT TO TAP SEWER

MASSILLON, OHIO, 6/18

RECEIVED OF

Harry Anton

FEE OF \$2.00

FOR WHICH PERMISSION IS GRANTED

John Burzda

TO TAP

Sanitary

SEWER, ON THE

East

OF

18th St. S.W.

AVE.,
ST.,

TYPE OF STREET

Land runoff

THE PREMISES BEING LOT No.

3285

HOUSE No.

928

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harry Anton

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.