## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 9-7-4	IF SO HOW AND LOCATION FROM 278 9 dech
HOUSE NO. 1726-172	$\underline{\mathscr{E}}$
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Bluestone
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR DIVISION O
SHOW BY DIAGRAM RELATION OF	LATERAL TO WALL OF BUILDING SERVED.
1520 57.	
: 1985년 1일 전 1일	
	1 The state of the
	$12 \times 177$
, 1	
SIGNED CALL	FILED AT ENGINEER'S OFFICE
INSPECTOR FO	
Bertan State of the section of the s	edirellerate of insula a tachind to slave
REMARKS:	a programment de la composition de la c La composition de la

## N? 4973 PERMIT TO TAP SEWER

	Massillon, Ohio,
	RECEIVED OF MAI AM ENTE
F	or which permission is granted Alimb
<b>T</b> 1	O TAP SEWER, ON THE
•	F 15th SE AVE., TYPE OF STREET ALL
τ,	HE PREMISES BEING LOT NO. 1298-88, HOUSE NO. 1726417
and the first first	ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUN
	ules of the Department of Public Service.  Ame of Contractor M. Bluotane

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.