

Nº 4976

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-4-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. Rear 104

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6

See Sketch


WAS LATERAL AT CURB? No.

WAS ATTACHED TO MAIN See Sketch

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE 9-9-47

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4976

PERMIT TO TAP SEWER

6/27

MASSILLON, OHIO,

RECEIVED OF

Roy Hambach

FEE OF \$2

FOR WHICH PERMISSION IS GRANTED

Roy Hambach

TO TAP

Sanitary

SEWER, ON THE

OF

Stanton NW

AVE.
ST.

TYPE OF STREET

dirt

THE PREMISES BEING LOT NO.

3770 - 3771

HOUSE NO.

Rear 231
24th St

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
 RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Harvey Astor

Note. This permit covers work outside of building only. Any work
 walls of building is subject to Massillon Board of Health Regulations.