

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº 4980

DATE INSPECTED 7-15-47

**IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM** 49

HOUSE NO. 746

**DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH** 49- 6' deep

SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? yes


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

14TH ST. S.E.

N



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

7-7-47 H

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4980

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7-7RECEIVED OF Earl MarshallFEE OF \$ 2FOR WHICH PERMISSION IS GRANTED Harvey AstonTO TAP SanitarySEWER, ON THE EastOF 14TH ST. SE.AVE., TYPE OF STREET Dirt
ST.THE PREMISES BEING LOT NO. 8297 & 8298HOUSE NO. 746

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harvey Aston

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.