

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-25-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1823

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes.

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

N^o 4987

PERMIT TO TAP SEWER

MASSILLON, OHIO, 7/25RECEIVED OF Harvey AstonFEE OF \$ 3FOR WHICH PERMISSION IS GRANTED Wm. KunkleyTO TAP SewSEWER, ON THE SOF Main StAVE.,
ST.,TYPE OF STREET AlcedTHE PREMISES BEING LOT NO. 10329HOUSE NO. 1823

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Aston

Note. This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.