## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-31-4	7 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO. 8/3	DISTANCE FROM FIRST MANHOLE の		
SIZE OF PIPE USED	GURB LINE AND DEPTH	80	4 Deep
WAS LATERAL AT CURB? / CS	- Section - Sect		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR \D C	iger	
SHOW BY DIAGRAM RELATION OF I	LATERAL TO WALL OF BUILDING SERVED.		Founa
	<b>.</b>		1 nots
	and the second of the second o	15/5	
		、レンドフ	Deck
en de la companya de La companya de la co	ii saarigaa emerenakinden ii seeli t	<b>火</b> !	
	Deep w	8	Approx. W. Cur
			o chain!
SIGNED R. J.	FILED AT ENGINEER'S	- <del>  80'</del>	<b>-</b>
NEFECTOR FOR	CITY	9/	17/2/1
REMARKS:	ga noimeen a jastabe el sociama i		47/

4992

## Nº 4992 PERMIT TO TAP SEWER

		ader adutacosadia vice di adari Myod diaperaa	Masgillon, Ohio,	7/30
feet	RECEIVED OF	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Bog.	FEE OF \$ 2 -
FO!	R WHICH FERMISS	ON IS GRANTED / V	WER, ON THE	west
OF	12	11 M. AVE.,.	Type of Street	dirt
	E PREMISES BEING		House No.	813
	化位用 医腹部部上外的 经经济发展	ACCORDANCE WITH ORDIN	ANCE NO. 2323, DULY PA	ASSED BY THE CITY COUN

NAME OF CONTRACTOR\_\_\_\_\_

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.