FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-5-47	- IF SO HOW AND LOCATION FROM SEE SKETCH
HOUSE NO. 93	마는 것은 마음에 들어왔다. 그는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들이 되었다. 그는 사람들이 되었다. 그는 사람들이 되었다. - 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURBY No.	NAME OF CONTRACTOR Albresht
SHOW BY DIAGRAM RELATION OF LA	TERAL TO WALL OF BUILDING SERVED. Found at not star
SAPPROX, W.C	orbline 8'x6"Y 410
Exist M.H. at 23rd & alleman	8" Main Line 7' Deep 56 FILED AT ENGINEER'S OFFICE
INSPECTOR FOR CI	Ty and the constraint of the c

4995

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

 N_{\cdot}° 4995

PERMIT TO TAP SEWER

				S_{i}	1
erlo	RECEIVED OF	len) 1	MASSILI LUI OAF	on, OHIO, /	FEE OF \$
	FOR WHICH PERMISSION	IS GRANTED	sanfe		Less socials
TOR	то тар	26/10/20 30 30 30 30 30 30 30 30 30 30 30 30 30	SEWER, ON THE		igovita bask Alo to modebil
	of (3/1/		VE. TYPE OF STR	EET . Had	<u>D</u> RUNA B
	THE PREMISES BEING LOT	No.1			
	RULES OF THE DEPARTME	自由1997年,其中大学的大学、自由自己的特殊的特点。	ICE.	a d	
	NAME OF CONTRACTOR	<u> (13,6</u>		breelf	

Note. This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.