

Nº 5006

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

3
27
✓

DATE INSPECTED 8-6-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 37

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

104' 7' Deep


WAS LATERAL AT CURB? Yes.

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

R. F. Smyke
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 5006

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, _____ 194

RECEIVED OF H. J. Aston FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED Clarence Myers

TO TAP Sanitary SEWER, ON THE South SIDE

OF Forest S.E. AVE., TYPE OF STREET Paved
ST.,

THE PREMISES BEING LOT No. 10375, HOUSE No. 39

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. J. Aston

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.