

Nº 5011

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

7
51

DATE INSPECTED 9-12-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1234

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

262' 7' deep

WAS LATERAL AT CURB? Yes



WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR

Earley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Johnson. St. S.E.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

12/1/47

REMARKS:

Nº 5011

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 5/7/47

194

RECEIVED OF

Ed. Blunt

FEE OF \$

2.00

FOR WHICH PERMISSION IS GRANTED

Rebt Adams

TO TAP

Sanitary

SEWER, ON THE

East

SIDE

OF

Johnson SE.

AVE., TYPE OF STREET

St.,

Dirt

THE PREMISES BEING LOT NO.

52438242

HOUSE NO.

1234

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

~~Ed. Blunt~~ D. Earley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.