

Nº 5013

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-29-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 1869

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 323' 7' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Bemlex

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Jefferson Ave N.E.



SIGNED

John Ehmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/9/47

REMARKS: _____

Nº 5013

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/11 1947RECEIVED OF James E. YermanFEE OF \$ 2.05FOR WHICH PERMISSION IS GRANTED sameTO TAP San.SEWER, ON THE S

SIDE

OF Jefferson NEAVE.,
ST.,TYPE OF STREET dustTHE PREMISES BEING LOT NO. 8110-8111HOUSE NO. 1869

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR A. Remley

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.