

Nº 5016

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-7-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 732

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
UP ~~DOWN~~ STREAM TO DITCH AT
CURB LINE AND DEPTH

230'

6' Deep.

WAS LATERAL AT CURB? YES


WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N ←



Foundation not
started.

6' Deep

Approx. E. Curb Line

Main Sewer

SIGNED

R. F. Snyder
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS: _____

Nº 5016

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 10/7 1947

RECEIVED OF H. Astor

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED Wm. Dall

TO TAP San

SEWER, ON THE E

SIDE

OF Bernard St.

AVE.,
ST.,

TYPE OF STREET Dist

THE PREMISES BEING LOT NO. 4640

HOUSE NO. 732

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR H. Astor

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.