

Nº 5017

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

6
2
1

DATE INSPECTED 8-23-77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 820

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 212 5' deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Smart

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Bennington Ave. N.E.



SIGNED John Chinner

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

Nº 5017

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO. 8/14 1947
RECEIVED OF J. Harry Schaefer FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED Thos. H. Hyelap
TO TAP San SEWER, ON THE N. SIDE
OF Bennington N.E. AVE., TYPE OF STREET Alley
ST.
THE PREMISES BEING LOT NO. 8523 + PL 8524 HOUSE NO. 820

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Smart

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.