

Nº 5018

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

14  
3  
1

DATE INSPECTED 8-19-47

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1305

SIZE OF PIPE USED 4"

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH

103 6' deep

WAS LATERAL AT CURB? yes



WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Bemley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Erie ST. S.



SIGNED

John Elmer  
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

REMARKS:

Nº 5018

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/18 1917

RECEIVED OF Raymond Remy

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED David Eder

TO TAP San

SEWER, ON THE N

SIDE

OF Eric S

AVE.,  
ST.

TYPE OF STREET Paved

THE PREMISES BEING LOT No. 7113

HOUSE No. 1305

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE No. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR R. Remy

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.