

Nº 5019

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

10/9
22/1

DATE INSPECTED 8-

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____



HOUSE NO. Rear 1125

SIZE OF PIPE USED 6" up DISTANCE FROM FIRST MANHOLE
6' 3'6" deep ~~STREAM~~ TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? Tapped in.

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR Earley
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Rear 14th ST. SE



SIGNED

John Chinner
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

Nº 5019

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO.

1947

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER, ON THE

SIDE

OF

AVE., TYPE OF STREET
ST.,

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.