

Nº 5021

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

2
22
✓

DATE INSPECTED 8-23-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 221

SIZE OF PIPE USED 4" up DISTANCE FROM FIRST MANHOLE
~~DOWN~~ STREAM TO DITCH AT 23' CURB LINE AND DEPTH 4'6" deep


WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR Remley

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Penn Ave, S.E.



SIGNED John E. Egan

INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE _____

REMARKS: _____

Nº 5021

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 8/20

1947

RECEIVED OF P. Remley

FEE OF 2.00

FOR WHICH PERMISSION IS GRANTED Acme Coal Co

TO TAP Sum

SEWER, ON THE S

SIDE

OF James E

AVE., TYPE OF STREET James
St.,

THE PREMISES BEING LOT NO. PA 44 Co

HOUSE NO. 221

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND
RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Remley

Note. This permit covers work outside of building only. Any work inside
walls of building is subject to Massillon Board of Health Regulations.