

N^o 5026

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-29-47

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. 939

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 28' 2'-6" deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Aston

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9TH ST. N.E.



SIGNED

John Elmer
INSPECTOR FOR CITY

FILED AT ENGINEER'S OFFICE

9/9/47

REMARKS: _____

N^o 5026

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE

PERMIT TO TAP SEWER

MASSILLON, OHIO. 8/28 1947
RECEIVED OF Harvey Aston FEE OF \$ 2.00
FOR WHICH PERMISSION IS GRANTED A. A. Zimmerman
TO TAP Sanitary SEWER, ON THE West SIDE
OF 9th W E AVE., TYPE OF STREET oiled
THE PREMISES BEING LOT NO. 7527, HOUSE NO. 939

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 2323, DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Harvey Aston

Note. This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.